



JON M. HUNTSMAN, JR.  
Governor  
GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director  
JOHN R. BAZA  
Division Director

80430011  
Incoming

0003

**Inspection Report**  
**Minerals Regulatory Program**  
**Date: December 9, 2008**

Reviewed: LR

<b>Mine Name:</b> Henefer Stockpiles	<b>Permit Number:</b> S/043/0011
<b>Operator Name:</b> Interstate Brick Company	<b>Inspection Date:</b> 12/04/2008
<b>Inspector(s):</b> Brett Gregory for Leslie Heppler	<b>Time:</b> 12:00 PM
<b>Other Participants:</b> None	<b>Mine Status:</b> Inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Bond Amount:** \$18,600

**Permit fee:** Current.

**Purpose of Inspection:** This was a routine annual inspection of the site.

**Inspection Summary:** Photos are attached.

- 2) The bike jumps present a safety hazard and the operator should evaluate their liability.  
6) The previous inspection of this site had documented that the clay stockpile was from the landfill expansion by the county. It appears no more material has been added to this existing stockpile. Large amounts of Russian thistle have grown and only a small amount of clay has been removed on the east side (see photographs). Operator should consider controlling invasive weeds to help assure successful final revegetation efforts.

**Conclusions and Recommendations:** Recommended that the operator post appropriate no trespassing signs to keep public out of the permitted area. DOGM will continue to monitor this site.

**Inspector's Signature**

BG:vs

cc: John Hewitt

O:\M043-Summit\M0430011-HeneferStockpiles\inspections\insp-12042008.doc

*[Handwritten Signature]*

Done  
8-18-09

RECEIVED

SEP 29 2009

DIV. OF OIL, GAS & MINING

Meeting in  
PIC office  
w/ Frank  
Response  
to inspect  
See photos  
Sept 29 AM

0003



Stockpile highwall.



Russian thistle.



Rain runoff into the field – Operator to evaluate and remediate.



Berm has been breached.





Garbage to be removed.



Bike jumps that can be a safety hazard.



Southern berm.



View of the top of the stockpile.



























